

T-11300/2

11/26/80

REPLACE DIGESTER COVER, DIGESTER S-716, HADNOT POINT SEWAGE TREATMENT PLANT

The digester at this plant was built in 1943. The digester composition roof has cracks and holes in it; the rain has kept the rafters and sheathing wet, and they have rotted. The metal supports in the cover have rusted and pitted to the point that their structural integrity has been affected. Accordingly, the entire digester cover should be replaced.

Estimated Cost: \$49,950

11-21-18


REPORT OF THE DIRECTOR OF THE BUREAU OF PLANT INDUSTRY

The following is a report of the results of the investigation conducted by the Bureau of Plant Industry during the year 1918. The investigation was conducted in accordance with the provisions of the Act of March 3, 1907, and the Act of August 2, 1914, and the results are reported in this report.

Approved: \_\_\_\_\_  
Director

DWG. 1. DIGESTER COVER.


35' FT DIA.



PROJECT NO 6

REPLACE DIGESTER COVER.

- 1- [Faint handwritten text]
- 2- [Faint handwritten text]
- 3- [Faint handwritten text]
- 4- [Faint handwritten text]
- 5- [Faint handwritten text]



11/26/80

REPLACE DIGESTER COVER, DIGESTER S-717, HADNOT POINT SEWAGE TREATMENT PLANT

The digester at this plant was built in 1943. The digester composition roof has cracks and holes in it; the rain has kept the rafters and sheathing wet, and they have rotted. The metal supports in the cover have rusted and pitted to the point that their structural integrity has been affected. Accordingly, the entire digester cover should be replaced.

Estimated Cost: \$49,950

10/10/80

UNITED STATES DEPARTMENT OF JUSTICE, FEDERAL BUREAU OF INVESTIGATION

The attached copy of this document is being furnished to you for your information. It contains information that is confidential and its disclosure is limited to you and your authorized personnel. This information is being furnished to you under the provisions of the Freedom of Information Act, 5 U.S.C. 552, and is not to be disseminated outside your organization. If you have any questions regarding this document, please contact the person whose name and telephone number are listed on the cover page of this document. This document is being furnished to you in accordance with the provisions of the Freedom of Information Act, 5 U.S.C. 552, and is not to be disseminated outside your organization.

Approved: [Signature] Special Agent in Charge

11/26/80

REPLACE DIGESTER COVER, DIGESTER S-718, HADNOT POINT SEWAGE TREATMENT PLANT

The digester at this plant was built in 1943. The digester composition roof has cracks and holes in it; the rain has kept the rafters and sheathing wet, and they have rotted. The metal supports in the cover have rusted and pitted to the point that their structural integrity has been affected. Accordingly, the entire digester cover should be replaced.

Estimated Cost: \$49,950

11/22/80

ESTIMATED COSTS OF THE TREATMENT PLANT

The design of the treatment plant is based on the design of the existing plant. The design of the treatment plant is based on the design of the existing plant. The design of the treatment plant is based on the design of the existing plant.

ESTIMATED COSTS OF THE TREATMENT PLANT